Facility ID#:

| UST CLOSE INSPECTION CH | |
|--|----------------------------------|
| Inspector's Name Kage | Date_ 630.94 |
| I <u>SITE INFORMATION</u> | |
| Facility/Site Name: PM Electroplating | |
| City/Town: High Point | County: Gu |
| Owner: PM Electroplating Operator: " | Phone: |
| Contractor: Legacy | Phone: |
| Laboratory: | Phone: |
| Directions: | |
| Date of scheduled UST Removal (from GW/US | T-3): |
| II <u>UST STATUS</u> | |
| Tank #: 1 2 3 4 Size: 20 € | 5 6 7 8 |
| Product: #ZEELOII | |
| Remark Y (YES), N (NO), NA (NOT APPLICABLE), and U (UNKNOWN) for each | of the following: |
| III CLOSURE PROCEDURES | |
| U Tanks, tools, equipment bonded or good OSHA/Safety violations observed: | rounded? |
| | |
| Product in piping drained into tank | ? |
| Y Tanks properly purged? Method: | • |
| Tanks emptied and cleaned properly? | |
| Accessible openings capped or plugged NA UST(s) closed in place and filled with the state of the | ed except 1/8" vent? |
| Tailer describedion of tank(s): Falls Sacco | - E |
| Final destination of product, contaminated | i soil, contaminated water, etc. |
| | |
| IV <u>SITE DESCRIPTION</u> | |
| | |
| Soil stained and/or petroleum odor? | |
| N Contaminated soil excavated? Quantit N Soil samples taken of excavated soil | :y? (estimate): |
| excavated soil on plastic or trucked away? | Circle one) |
| rank(s) condition: +aic | (011010 0110) |
| Product line condition?: | |
| Note: Many limbs/roots etc. | |
| V SAMPLING LOCATION | |
| NA USTs < 20': one at each end? | |
| USTs > 20': one at each end & middle | |
| <u>NA</u> Samples every 20' of piping? NO pun | · ир. |
| <u>NR</u> Samples under each tank island? ' | |
| N Water samples? (in lieu of soil samp | les) |
| Samples: floor, side, stockpiled soil?: | |
| | |
| · · · · · · · · · · · · · · · · · · · | |

Facility ID#:

| VI SAMPLE COLLECTION QUALITY CONTROL |
|--|
| Collection method: (Shovel, auger, back hoe): How Preserved? (ice): Tools decontaminated: (soap, Di-H ₂ O, MEOH, organic-free H ₂ O). Chain-of-Custody form (required): |
| VII SUMMARY OF SITE CONDITIONS |
| N Groundwater intersected? N Bedrock encountered? Y Contaminated soil? N Free product in excavation? |
| VIII SAMPLES COLLECTED BY DEM PERSONNEL |
| N Samples collected? Sample locations: |
| XV COMMENTS: |

31'2 × 10'6" d

DIAGRAM OF SITE INVESTIGATION AT UST CLOSURE

Diagram should include physical structures such as roads, buildings, etc.; former location of USTs, pumps, product lines; soil sampling locations; and location of excavated soil.

